

# Assembly instructions

Product: SA1100/1500	Service description no: 2613-M003	Ver: 1
-------------------------	---	-----------

## Shafting

To get more tightening on the sealing hatch, the shaft (A) must be replaced with item number 1261176.

Remove the screws marked (B) and (C) and pull out the shaft. Insert new shaft and reassemble the screws.

