

# Service description

Product: SP200	Service description no: 3112-S003	Ver: 1
-------------------	---	-----------

## Symptom

Replacement of cutter.

## Caused by

The cutter is deformed or worn.

## Solution

Replace the cutter with a new one.

Release four screws that hold the cutter.



Apply Loctite and attach a new ring.

