

Service description

Product: SP200	Service description no 3112-S010	Ver: 1
-------------------	--	-----------

Symptom

The double gearbox at the bottom of the pump holder is loose.

Caused by

The part of the double gearbox that points away from the tractor must NOT be completely screwed in.

Solution

The gearbox is attached to the bracket that should fit loosely against the pump attachment. This is to avoid tension in the gearbox during start-up and moving the pump. DO NOT tighten the screw marked in the picture.

