

Service description

Product: SP400	Service description no: 3125-S003	Ver: 1
-------------------	---	-----------

Symptom

The cutter replacement.


Caused by

The pump is used a lot and the cutter is the wearing part.

Solution

Replace the cutter with a new one.

Release the four screws that hold the cutter.



Apply Loctite and attach a new ring.

