

Service description

Product: VM420	Service description No.: 4120-S003	Ver: 1
-------------------	--	-----------

Symptom

The elevator belt runs slowly during cutting

Caused by

1. The cylinder operating the saw movement consumes oil from same circuit as the elevator belt. This will reduce the elevator belts speed somewhat when the cylinder is activated.

Solution

1. Adjust power and speed of this movement as described in the instructions manual..