

## Service description

Product: SP200	Service description no: 3112-S012	Ver: 1
-------------------	---	-----------

### **Changing the oil on the double gearbox inclined pump and combination pump.**

On newer pumps with GB gearboxes, there is a drain plug under the gearbox. On these pumps, just drain the oil in the usual way.

On older pumps with BYPY and Comer gearboxes, you must use an oil pumper or release the gearbox to empty it.

It is advisable to flush the gearbox with diesel, for example, and have it properly cleaned before filling the gearbox with a new oil.