

Service description

Product: PT280	Service description no: 3222-S001	Ver: 1
-------------------	---	-----------

PT280 serial number fom. 200005 up to 210020

Symptom

1. The gearboxes leak oil through the air plugs.
2. The safety funnel melts.

Caused by

1. Too much oil in the gearboxes.
2. Wrong type of safety funnel that is not designed for heat.

Solution

1. Reduce the amount of oil in each gearbox from 1.6 liters to 1.3 litres.
2. Replace the safety funnels with a new type. New safety funnel has item number 2962137.

Send an email to post@duun.no and specify the serial number and problem, and we will send new safety funnels.