

Service description

Product: VM420	Service description No.: 4120-S006	Ver: 1
-------------------	--	-----------

Symptom

The saw motor starts when operating the knife elevation-adjustment.

Cause

1. Hydraulic pressure in the return pass from the joystick. This pressure triggers a slight movement of the cylinder moving the saw bar downwards.

Solution

1. Mount a one way valve for this circuit..