

Service description

Produkt: VM 420	Servicemeldingsnr: 4120-S027	Ver: 1
--------------------	---------------------------------	-----------

Symptom

Speed regulation for the saw does not work. Difficult to adjust the speed of the saw
Saw picks and go at different speeds.

Cause

Return valve in the control valve for speed not working.

Solution

Disassemble valve for speed control of the saw and remove any impurities. The valve body need not be removed. (See picture)
Alternatively, install a new valve into the block.

