

Service description

Product: VM420	Service description No.: 4120-S029	Ver: 2
-------------------	--	-----------

Symptom

The power adjustment for the saw bar movement does not function and do not respond to adjustment
The saw bar do not have any power and do not manage to move downwards despite the saw chain is rotating.

The saw bar moves downwards with high power and the saw chain rotation stops.

Cause

The safety valve regulating power does not operate.

Solution

Dismount the valve regulating movement power for the saw bar and remove eventual contaminant.

The valve itself does not need to be dismounted (See picture)

Eventually replace the valve pictured.

