

## Service description

Product: VM370	Service description no: 4131-S002	Ver: 1
-------------------	--------------------------------------	-----------

### Symptom

The conveyor belt stops and locks up

### Caused by

The chain wheel which drives the conveyor chain slips against the hydraulic motor and becomes heavier.

### Solution

Replace the set screw that locks the chain wheel onto the shaft.  
Order a new set screw that has a hollow end and fits better against the shaft.

Item number: 2473237

It is important to use Loctite på set screw.

